# Energy performance certificate (EPC) recommendation report

Rankin Hall Duke Street ASKAM-IN-FURNESS LA16 7AE Report number 8632-5420-5478-4099-4633

Valid until 23 February 2034

### **Energy rating and EPC**

This property's energy rating is E.

For more information on the property's energy performance, see the EPC for this property.

## Recommendations

## Changes that may pay for themselves within 3 years

| Recommendation   | Potential impact on<br>carbon emissions |
|--|---|
| Add time control to heating system.  | Low                                     |
| In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows. | Medium                                  |
| Add optimum start/stop to the heating system.  | Medium                                  |
| Changes that may pay for themselves within 3 to 7 years  |   |
| Recommendation   | Potential impact on<br>carbon emissions |
| Some walls have uninsulated cavities - introduce cavity wall insulation.   | Medium                                  |
| Consider replacing T8 lamps with retrofit T5 conversion kit.   | Medium                                  |
| Some windows have high U-values - consider installing secondary glazing.   | Medium                                  |
| Add local temperature control to the heating system.   | Medium                                  |
| Add weather compensation controls to heating system.   | Medium                                  |
| Some loft spaces are poorly insulated - install/improve insulation.  | Medium                                  |
| Add local time control to heating system.  | Medium                                  |
| Some solid walls are poorly insulated - introduce or improve internal wall insulation.   | Medium                                  |
| Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.   | Medium                                  |
| Changes that may pay for themselves in over 7 years  |   |
| Recommendation   | Potential impact on<br>carbon emissions |
| Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.   | Low                                     |
| Some glazing is poorly insulated. Replace/improve glazing and/or frames.   | Medium                                  |
| Roof is poorly insulated. Install or improve insulation of roof.   | Medium                                  |
| Consider installing PV.  | Low                                     |
|  |   |

# Property and report details

| Report issued on        | 24 February 2024                            |
|-------------------------|---|
| Total useful floor area | 150 square metres                           |
| Building environment    | Heating and Natural Ventilation             |
| Calculation tool        | G-ISBEM Ltd, G-ISBEM, v25.3, SBEM, v6.1.e.0 |

#### Assessor's details

| umbria LA21  |
|--------------|
|              |
| owner of the |
|              |
| _            |